



GARY R. HERBERT  
Governor

GREGORY S. BELL  
Lieutenant Governor

# State of Utah

## DEPARTMENT OF NATURAL RESOURCES

MICHAEL R. STYLER  
Executive Director

### Division of Oil, Gas and Mining

JOHN R. BAZA  
Division Director

## Inspection Report Minerals Regulatory Program August 2, 2010

Reviewed: 

<b>Mine Name:</b> Cloudy Moon	<b>Permit Number:</b> S/037/0116
<b>Operator Name:</b> Moon Mountain Stone	<b>Inspection Date:</b> May 11, 2010
<b>Inspector(s):</b> T Munson	<b>Time:</b> 3:00 PM
<b>Other Participants:</b> none	<b>Mine Status:</b> active

### Elements of Inspection

1. Permits, Revisions, Transfer, Bonds
2. Public Safety (shafts, adits, trash, signs, highwalls)
3. Protection of Drainages / Erosion Control
4. Deleterious Material
5. Roads (maintenance, surfacing, dust control, safety)
6. Reclamation
7. Backfilling/Grading (trenches, pits, roads, highwalls, shafts)
8. Soils
9. Revegetation

Evaluated	Comment	Enforcement
<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>
<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>
<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>

**Bond Amount:** \$10,000

**Fees:** Delinquent since 2007

**Purpose of Inspection:** To inspect reclamation.


### Inspection Summary:

The site consist of two small digs. The sites were reclaimed in 2008 and seeded at this time. Some native vegetation has moved into the sites to make it reasonable to release. The overall area surrounding the site is dominated with Pinyon Juniper with very little understory. In conversations with John Blake of SILTA, it was agreed that releasing the site would be appropriate.

Photos were taken to document site conditions.

### Conclusions and Recommendations:

The operator has an outstanding violation fine that needs to be paid. The site is reclaimed.

**Inspector's Signature** 

TM:vs

cc: Johnblake@utah.gov

O:\M037-SanJuan\S0370116-CloudyMoon\Inspect\insp-05112010.doc







Reclaimed site



Site is regraded with marginal vegetation



Site is regraded with marginal vegetation



Natural vegetation is Pinyon/Juniper with very little understory